








Photo 2—Panel Point L1', Downstream Truss. Note tensile failure of floorbeam hanger plates.



Photo 3—Panel Point L1',
Downstream Truss. Note
severe deformation of
vertical member L1'-U1'.











2015.04.01 13:28



2015.04.01 13:29





























**For additional information concerning the
Marion County Engineer's Office please
visit:**



<http://www.co.marion.oh.us/engineer>

or

Google "Marion County Engineer Ohio"